



1/10





FIG. 1






FIG. 2
(Prior Art)

3/10




FIG. 3

4/10




FIG. 4

5/10




FIG. 5

6/10




FIG. 6

7/10




FIG. 7

8/10




FIG. 8

9/10





FIG. 9

10/10



$$H_0 = -\frac{R_2}{R_1}$$

$$\omega_0^2 = \frac{1}{C_1 C_2 R_2 R_3}$$

$$\frac{\omega_0}{Q} = \frac{1}{C_1} \left(\frac{1}{R_1} + \frac{1}{R_2} + \frac{1}{R_3} \right)$$

$$R_y = \frac{1}{2\omega_c^2 C_2} \frac{\omega_0}{Q}$$

$$C_y = \frac{2}{R_y} \frac{1}{\omega_0} = 4\omega_c^2 C_2 \left(\frac{\omega_0}{Q} \right)^2$$

$$R_x = \frac{1}{\omega_c C_2}$$

$$C_x = \frac{1}{R_x \frac{\omega_0}{Q}} = \frac{\omega_c C_2}{\frac{\omega_0}{Q}}$$

FIG. 10